



RESISTANCE A-WING FIGHTER™
MMS416



It is highly recommended that you visit www.metalearth.com/360/mms416 to see the completed model before assembling your own

Legends:

- E Engraved/Color side
- NE Non-engraved/Silver side
- Attention point
- Insert tab and bend 90 degrees
- ▲ Insert tab and twist 90 degrees

Assembly tip:
If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

Assembly Flow Chart

A-1 [Diagram of wing assembly]

B-2 [Diagram of sensor assembly x2]

C-3 [Diagram of sensor assembly]

C-4 [Diagram of sensor assembly]

A-5 [Diagram of sensor assembly]

A-6 [Diagram of sensor assembly]

C-7 [Diagram of sensor assembly x2]

A-8 [Diagram of sensor assembly]

A-9 [Diagram of sensor assembly]

A-10 [Diagram of sensor assembly x2]

Metal sheets

A Parts that are in the same color are duplicates

B

C

In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed





