



Scorpion
Item No. MMS070



It is highly recommended that you visit www.metal-earth.com/360/mms070 to see the completed model before assembling your own

Legends:

- Engraved side
- Non-engraved side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

Assembly tip:
If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Diagram: A small diagram showing a metal part with an insertion tab and an insertion hole. Labels indicate: "Insertion tabs are inserted and then folded", "Fold lines can be seen as shown here", and "Insertion holes".

Metal sheet



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

Engraved side faces down

7 x 5

21 x 5

22 x 5

23 x 5